

BUILDING SAFETY CERTIFICATE

No. -22

Dated: 18/06/2024

It is certified that the existing building Chakrapani Residential School (name of the building or premises) at Rajgir Chhabilapur Road, Rajgir Nalanda, Bihar (address) is having block(s)/Floor (s) as per details below:

Details of Block(s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	3	N/A	N/A	N/A	N/A	N/A

The building is owned/occupied by Chakrapani Residential School (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Building Sub Division

(Name of Department/ Govt.) on 14/06/2024 (date of inspection) in the presence of Dr. Vishwendra Kumar Sinha / Meena Kumari, Chakrapani Residential School, Rajgir, Chhabilapur Road, Rajgir

(name and addresses of the manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from

for a period of One years in accordance with rule and subject to compliance of the specific conditions as appended.

1. N/A
2. N/A
3. N/A
4. N/A

Issued on at Rajgir, Nalanda by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:



Assistant Engineer
Building Sub-Division, Rajgir

Name: SAUMYA SAURABHDesignation: Assistant Engineer

Name & Address of Department/Office:

Rajgir BCD / Biharsharif
Nalanda Bhaban Pramand